



Manufacturer Defect: Enoxaparin (Inhixa) 40mg/0.4mL injection

Information for:

Pharmacy ✓

Nurses ✓

- Pharmacy have been made aware of a fault with a batch of **Enoxaparin (Inhixa) 40mg/0.4mL injection TTO packs**.
- The protective shield has been released prematurely preventing a dose from being given.
- All TTO packs of enoxaparin should be checked prior to supply.
- Do **NOT** use or supply LOT number AB04531A. Please quarantine and return to pharmacy.
- Vigilance to the integrity of the protective sheath is recommended when using or supplying any enoxaparin.
- Report any faults to pharmacy immediately

Issued 10th April
2021

Contacts:
Medicines
Information ext.
8153

Medication Safety
Officer ext. 63327

Divisional Lead
Pharmacists ext.
63210/62597